

---

## Interventie service BC 3000 +

I.D.: 48388102

---

Data publicarii	24.07.20	Coduri CPV	50421000-2
-----------------	----------	------------	------------

---

Pretul estimativ: 1.680,67 RON - 1.680,67 RON

---

Descriere: Interventia include inlocuirea urmatoarelor piese: - Probe wiper x 1 buc. 686 - Filtru de aer x 4 buc (111 RON/buc) 444 - Cap piston seringa 10mL x 1 buc. 550.67 Manopera service x 3 ore (gratuit conform contract service) Transport service (gratuit conform contract service)  
PREZENTA TINE LOC DE COMANDA

---