
Servicii de reparat masina de spalat rufe

I.D.: 43977264

Data publicarii	10.09.19	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ:	293,00 RON - 293,00 RON
-------------------	-------------------------

Descriere:	verificare constatare si schimbat pompa de evacuare apa
------------	---
