

Servicii de reparare a SM15PCA

I.D.: 62751837

Data publicarii	04.11.21	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 1.862,31 RON - 1.862,31 RON

Descriere: MATERIALE: FILTRU ULEI - 1 X 31.93 RON + TVA FILTRU,AER HABITACLU (POLEN) FARA CARBON ACTIV - 1 X 73.95 RON + TVA FILTRU COMBISTIBIL - 1 X 52.10 RON + TVA FILTRU AER - 1 X 92.44 RON + TVA ULEI CASTROL EDGE 5W30 / 4 L - 1 X 183.19 RON + TVA CASTROL EDGE 5W30/1L - 4 X 46.22 RON + TVA SAIBA CUPRU - 1 X 2 RON + TVA DISC FRANA FATA - 2 X 231.93 RON + TVA SET PLACUTE FRANA FATA - 1 X 158.82 RON + TVA SET BUCSI DE GHIDAJ ETRIER FRANA FATA - 1 X 47.06 RON + TVA SENZOR UZURA FATA CU CABLAJ - 1 X 401.68 RON + TVA MANOPERA: DEMONTAT MONTAT ROATA 15C - 4 X 3.36 RON + TVA CENTRAT ROATA 15C - 4 X 9.24 RON + TVA SCHIMB ULEI + FILTRE - 1.50 X 80 RON + TVA
