
Servicii de reparare a masinii de tuns iarba VIKING 6.2 RH

I.D.: 101781092

Data publicarii	20.08.24	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ:	1.560,50 RON - 1.560,50 RON
-------------------	-----------------------------

Descriere: Servicii de reparare a masinii de tuns iarba VIKING 6.2 RH - inlocuire roti spate, bucsa cutit, pana bucsa cutit, cutir, volanta motor, pana volanta, filtru aer, ulei motor si sfori demaror
