
Reparatie Dacia Logan II 1,5 dCI; schimbat pompa apa, kit distributie si kit transmisie, inlocuit li

I.D.: 45326295

Data publicarii	17.02.20	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	1.048,22 RON - 1.048,22 RON
-------------------	-----------------------------

Descriere:	Reparatie Dacia Logan II 1,5 dCI; schimbat pompa apa, kit distributie si kit transmisie, inlocuit lichid racire
------------	---
