

Serviciu de reparare VW TRANSPORTER

I.D.: 97391110

Data publicarii	17.05.24	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 3.494,37 RON - 3.494,37 RON

Descriere: Servicii de reparare autovehicul VW TRANSPORTER ce includ:inlocuire conducta AC tur,freon134A, filtru antialergenic,ulei compresor,oringuri instalatie AC,legare la masa,bucsa bara stabilizatoare spate,colier, profil de ghidare,surub de sudare,panou metalic,materiale mici,diagnoza VAS5051,reconditionare alternator.
