

---

## **Reparatie pompa Wilo MVIE 208 (4077521/62804)**

I.D.: 99936816

---

Data publicarii	12.07.24	Coduri CPV	50511000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 3.125,62 RON - 3.125,62 RON

---

Descriere: Reparatie pompa Wilo MVIE 208 (4077521/62804), constand din: - schimbarea setului de etansare mecanica; - schimbarea setului de rulmenti (in motor 2 buc, la cuplaj 1 buc); - manopera aferenta.

---