
Reparatie maturatoare Johnston 142A, 101T(C50)

I.D.: 57087882

Data publicarii	18.05.21	Coduri CPV	50110000-9 50100000-6
-----------------	----------	------------	-----------------------

Pretul estimativ: 3.770,36 RON - 3.770,36 RON

Descriere: Reparatia include: Filtru ulei motor Johnston - 1 buc Filtru combustibil Johnston - 1 buc Filtru aer principal Johnston - 1 buc Filtru aer secundar Johnston - 1 buc Ulei motor MOBIL DELVAC XHP ESP 10W40 - 5,5 litri Materiale consumabile - 2 set Diagnoza computerizata suprastructura - 3,18 UT Verificare de integritate instalatie electrica de comanda suprastructura - 4,24 UT Verificare de integritate instalatie electrica de comanda cabina - 3.80 UT Remediere instalatie electrica - 1,24 UT Revizie motor (cuprinde: inl FU,PFC,FC,PFA,FA, ulei motor) - 2,25 UT Control de rampa - 1,84 UT Deplasare dus-intors
