
Reparatie Lexmark X950. Inlocuire cooler placa principala

I.D.: 101285534

Data publicarii	09.08.24	Coduri CPV	50310000-1 50323000-5
-----------------	----------	------------	-----------------------

Pretul estimativ:	500,00 RON - 500,00 RON
-------------------	-------------------------

Descriere:	Reparatie Lexmark X950. Inlocuire cooler placa principala
------------	---
