
Reparatie autoutilitara Toyoa Hilux B 14 LCX

I.D.: 43523209

Data publicarii	18.07.19	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 990,68 RON - 990,68 RON

Descriere: SERVICII DE REPARATIE AUTO TOYOTA HILUX -1051,18 LEI FARA TVA : - FREON 0,60KG; ADITIV DETECTOR FISURI AC 0,01L; COBDUCTA AC 1 - 728,08LEI FARA TVA; - MANOPERA - INLOCUIT CONDUCTA AC., INCARCAT SISTEM AC, REFACTURARE CONST FURTUNURI- 323,10 LEI FARA TVA
Referat nr. 3755/11.06.2019
