
Servicii de reparare masina de spalat profesionala Samsung

I.D.: 87270461

Data publicarii	21.09.23	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 980,00 RON - 980,00 RON

Descriere: Reparatie masina de spalat rufe profesionala Samsung WF431/14KG : inlocuit geam hublou , inlocuit sertar detergent , inlocuit racord cauciuc la DGASPC SECTOR 1 / MPRRN Alexandra
