
REPARATIE PERFUSOR SPACE seria 497154

I.D.: 77316045

Data publicarii	13.01.23	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.294,64 RON - 1.294,64 RON

Descriere: REPARATIE PERFUSOR SPACE seria 497154 DESCRIERE: REPARATIE PERFUSOR SPACE seria 497154 = 1294.64 LEI FTVA - PIESE SCHIMB: - 34502001 Lump Sum for Consumables (kit pentru reparatii) 1buc - 50.00 lei - 34520970 OPERATING UNIT, COMPLETE PSP (panou operare PSP) 1 buc - 834.24 lei - 34774386 COVER CAP CASE SP (capace suruburi echipament SP) 10buc - 1.04 = 10.40 - MANOPERA REPARATII +CALIBRARE+TSC 1buc - 400.00
