

Prestari servicii - Reparat masina de spalat

I.D.: 72975300

Data publicarii	08.09.22	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 924,37 RON - 924,37 RON

Descriere: Reparat masina de spalat Indesit: schimbat cuva, curatat furtune, filtre - 546.22 lei Reparat masina de spalat industrial ; schimbat curea, - 378.15 lei
