

---

## **Prestari servicii - Reparat masina de spalat**

I.D.: 72975300

---

Data publicarii	08.09.22	Coduri CPV	50800000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 924,37 RON - 924,37 RON

---

Descriere: Reparat masina de spalat Indesit: schimbat cuva, curatat furtune, filtre - 546.22 lei Reparat masina de spalat industrial ; schimbat curea, - 378.15 lei

---