
Servicii de intretinere VW TRANSPORTER

I.D.: 88345065

Data publicarii	17.10.23	Coduri CPV	50112200-5
-----------------	----------	------------	------------

Pretul estimativ:	1.075,50 RON - 1.075,50 RON
-------------------	-----------------------------

Descriere: Servicii de reparare si intretinere VW TRANSPORTER ce includ: inlocuire ulei motor 504/50700,buson baie ulei,filtru ulei, filtru aer,filtru polen, filtru combustibil, materiale mici.
