
REPARAT ABS DACIA DOKKER

I.D.: 63268889

Data publicarii	18.11.21	Coduri CPV	50100000-6
-----------------	----------	------------	------------

Pretul estimativ:	320,42 RON - 320,42 RON
-------------------	-------------------------

Descriere:	TEST DIAGNOZA,INLOCUIT SENZOR ABS STG FATA,LUCRARI ELECTRICE
------------	--
