

---

**reparat POMPA JUNG 0.85KW/3000T, reparat POMPA JUNG  
2.9KW/3000**

I.D.: 47313244

---

Data publicarii	15.06.20	Coduri CPV	50511000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 2.750,00 RON - 2.750,00 RON

---

Descriere: demontat si montat , rebobinat stator, inlocuiti rulmenti SKF, inlocuit etansare mecanica , inlocuit ulei, diverse; montat demontat bobinat inlocuit rulmenti SKF, inlocuit ulei SHELL, etansari mecanice

---