
SERVICII REPARATIE VW CADDY

I.D.: 104977187

Data publicarii	28.10.24	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ:	5.761,34 RON - 5.761,34 RON
-------------------	-----------------------------

Descriere: SCHIMB ULEI SI FILTRE SCHIMB KIT DISTRIBUTIE POMPA APA CUREA POMPA ULEI SCHIMB DISCURI SI PLACUTE FATA SCHIMB PLACUTE SPATE SCHIMB ANTIGEL DEMONTAT/MONTAT BAIE ULEI ETANSEIZARE BAIE ULEI
