



Servicii de reparatii si intretinere auto

I.D.: 102443701

Data
publicarii

05.09.24

Coduri CPV

50112000-3

Pretul
estimativ:

1.693,28 RON - 1.693,28 RON

Descriere: servicii: spalat interior exterior 210.08 lei manopera totala 840.34 lei D/M butuc spate + planetara si inlocuit schimb ulei diferencial spate inlocuit placute D/M saboti si reglat frana mana materiale: set placute frana spate 210.08lei ulei diferencial spate 3 l 277.31 lei simiring butuc spate 2buc 218.49 lei spray curatare 1 buc 33.61 lei silicon etansare buc 1 46.22 lei total 1693.28 lei
