
Servicii reparatie masini de spalat

I.D.: 100306960

Data publicarii	17.07.24	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 420,00 RON - 420,00 RON

Descriere: reparatie masina de spalat marca samsung . inlocuit pompa evacuare , piesa plus manopera 220 lei fara tva reparatie masina de spalat arctic , reparatie ansamblu motor , inlocuit perii motor, inlocuit furtun evacuare apa 200 lei plus tva
