

## Lucrari de reparatii instalatii termice

I.D.: 63204316

Data publicarii 18.11.21 Coduri CPV 45453000-7

Pretul estimativ: 32.309,12 RON - 32.309,12 RON

Descriere: Oferta refuzata: Lucrarile de reparatii instalatii termice: Brz OL FE 1 buc 1; Niplu bronz 1 buc 1; Teu bronz 1 1/4 buc 1; Colier metalic G 3/4 buc 115; Colier metalic G 1 buc 32; Colier metalic G1 1/2 buc 5; Colier metalic G4 buc 14; Garnitura kling hol 3/4 buc 8; Garnitura kling hol 1/2 buc 1; Gratar inox buc 1; NG ol Fi 1/2 buc 1; Racord filet interior 50\*1 1/2 buc 1; Adaptor filet exterior 20\*1/2 buc 40; Adaptor filet exterior 50\*1 1/2 buc 1; Adaptor filet interior 50\* 11/2 buc 2; Adaptor filet interior 63\*2 buc 1; Clema 20 buc 100; Clema 25 buc 50; Clema 32 buc 40; Clema 40 buc 11; Clema 50 buc 20; Cot 20/45 buc 69; Cot 20/90 buc 124; Cot 20\*1 1/2 filet exterior buc 40; Cot 20\*1/2 filet interior buc 5; Cot 25/45 buc 25; Cot 25/90 buc 62; Cot 32/45 buc 4; Cot 32/90 buc 17; Tub 40 fibra ml 4; Sac pp 550\*1000 buc 6; Tub 50 fibra ml 40; Tub 20 AL ml 40; Tub 25 AL ml 40; Robinet tur / retur 1/2 buc 60; Robinet HOL MT 1 1/2 arm buc 2 Robinet SF 1 1 /2 buc 2; Cot 40/90 buc 8; Cot 50/45 buc 10; Cot 50/90 buc 20; Dop 20 buc 2; Mufa 20 buc 16; Mufa 25 buc 32; Mufa 32 buc 8; Mufa 40 buc 1; Mufa 50 buc 10; OL FI 25\*3/4 buc 5; Reductie 25-20 buc 6; Reductie 32-25 buc 1; Reductie 63-50 buc 1; Robinet 20\*1/2 cu bila buc 6; Robinet 25\*3/4 cu bila buc 15; Teu 20 buc 30; Teu 25 buc 10; Teu 25\*20\*25 buc 15; Teu 32\*20\*32 buc 20; Teu 50 buc 2; Piesa CT 110 buc 9; Loctite buc 4; Mufa 40 buc 40 ;Mufa 25 buc 9; Reductie 50-25 buc 2; Niplu bronz 1 1/2 buc 2; Teu 50\*25\*50 buc 20; Diblu 8\*100 cap hexagobal buc 100