

---

## SET REPARATII BN77PLI

I.D.: 102446439

---

Data publicarii	04.09.24	Coduri CPV	50112200-5
-----------------	----------	------------	------------

---

Pretul estimativ: 5.680,67 RON - 5.680,67 RON

---

Descriere: BEC 12V 8X4.20, FILTRU ULEI 71.43, ULEI 5L 252.10, ULEI 1L 58.82, DISC FRANA 2X294.12, PLACUTE FRANA 168.07, DISC FRANA 2X210.08, PLACUTE FRANA 193.28, CABLU FRANA 2X92.44, BIELETA ANTIRULIU 2X92.44, CAP DE BARA 2X50.42, BIELETA DIRECTIE 2X50.42, BUCSA ARC 4X54.62, SIMERING 84.03, FILTRU AER 126.05, FILTRU COMBUSTIBIL 151.26, FILTRU POLEN 134.45, DISC DE TAIAT 4.20, VASELINA 67.23, COLIER PL 5X0.1.68, SIMERING 294.11, SIMERING 100.84, SURUB 29.41, SURUB , MANOPERA 56X30, REGLAT DIRECTIE 168.06, ITP 252.10.

---