

PIESE BRANSARE

I.D.: 60398013

Data publicarii 26.08.21 Coduri CPV 42132000-3

Pretul estimativ: 5.835,53 RON - 5.835,53 RON

Descriere: denumire um cantitate pret GARNITURA OLANDEZ 2" BUC 2 0.45 VANA POLIETILENA D90 BUC 1 505.55 TIJA VANA POLIETILENA BUC 1 197.07 MUFA EF D90 BUC 4 25.35 ROBINET APA 2" BUC 1 77.77 MUFA RAP D63*2"FE BUC 2 12.21 COT RAP D63 BUC 2 22.27 NIPLU ZN 2" AVIZ SANITAR BUC 2 11.25 MUFA RAP D63*2"FI BUC 2 11.6 TEAVA APA D90 PN10 - BARA ML 3 19.21 TEAVA APA D63 PN10 M 10 11.16 COT RAP D25*3/4"FE BUC 60 3.4 COLIER REPARATIE INOX DN150(155-165)L BUC 1 327 ROBINET APA 3/4" BUC 1 15 COT RAP D25*3/4"FE BUC 1 3.4 COT RAP D25*3/4"FI BUC 1 3.99 MUFA RAP D25 BUC 2 4.36 MUFA RAP D25*3/4FE BUC 2 3.24 MUFA RAP D25*3/4FI BUC 2 3.67 SA RAP D63*3/4" BUC 6 6.66 NIPLU ZN 3/4" AVIZ SANITAR BUC 16 3.36 MUFA RAP D25*3/4FI BUC 8 3.67 SA RAP D200*3/4" BUC 2 127.07 ROBINET APA 3/4" BUC 8 15 COLIER REPARATIE INOX DN150(155-165)L BUC 2 327 COLIER REPARATIE INOX DN125 (128-139)L BUC 1 297.67 TEAVA APA D40 PN10 M 20 4.54 MUFA RAP REDUSA 63/40 BUC 1 25.88 REDUCTIE ZN 2"-1 1/4" AVIZ SANITAR BUC 2 9.61 ROBINET FONTA 1/2" BUC 2 19.15 ROBINET FONTA 3/4" BUC 2 27 ROBINET FONTA 1" BUC 1 38 TEAVA APA D32 PN10 M 10 2.92 SA RAP D125*1" BUC 1 14.3 SA RAP D110*1" BUC 1 14.55 NIPLU ZN 1" AVIZ SANITAR BUC 4 3.76 VALVA POLIETILENA D32*1"FI BUC 2 33 MUFA RAP D32*1"FI BUC 2 3.36 MUFA RAP D32*1"FE BUC 2 3.53 MUFA RAP REDUSA 32/25 BUC 1 5.36 TEAVA PVC D400 SN4 6M BUC 2 865.05 TEU BRANSAMENT EF D200/63 BUC 1 182.52 MUFA EF D63 BUC 1 13.03 ROBINET APA 2" BUC 1 77.77 B FITING TRANZITIE D63*2"FE BUC 1 67.27 SA RAP D200*2" CU INEL BUC