

REPARATIE SI REVIZIE AUTO SKODA FABIA; REVIZIE SI REPARATIE SKODA OCTAVIA

I.D.: 88876763

Data publicarii 30.10.23 Coduri CPV 50110000-9

Pretul estimativ: 3.418,47 RON - 3.418,47 RON

Descriere: MATERIALE: Rola accesorii mobila 1x44.64=44.64 ; Ulei Mobil 10w40 1l 4x25.21=100.84 ; Filtru ulei1x20.17=20.17 ; Filtru aer 1x31.93=31.93 ; Filtru polen 1x33.61=33.61 ; Filtru benzina 1x65.55=65.55 ; Simering supape 6x4.20=25.2 ; Supapa admisie 3x33.61=100.83 ; Supapa evacuare 3x42.02=126.06 ; Kit distributie 1x527.73=527.73 ; Garnitura chiuloasa 1x117.65=117.65 ; Curea accesorii 1x70.59=70.59 ; Rola accesorii fixa 1x63.87=63.87
MANOPERA: DR baie ulei 2.00x58.82=117.64 ; DR distributie 5.00x58.82=294.1 ; DR chiuloasa 6.00x58.82=352.92 ; DR simering supape +supape si rectificat scaune supape 5.00x58.82=294.1 ; Revizie (ulei+filtre) 2.00x58.82=117.64
MATERIALE: Ulei Castrol edge 5w30 5l 1x260.50=260.50 ; Filtru ulei 1x23.53=23.53 ; Filtru aer 1x30.25=30.25 ; Filtru motorina 1x44.54=44.54 ; Placute frana fata 1x92.44=92.44 ; Placute frana spate 1x79.83=79.83 ; Bec H7 2x25.21=50.42 ; Bec stop frana1x12.60=12.60 ; Bec H1 1x25.21=25.21
MANOPERA: Revizie (ulei+filtre) 2.00x58.82=117.64 ; DR placute frana fata 1.00x58.82=58.82 ; DR placute frana spate 1.00x58.82=58.82 ; Test franare 0.43x58.82=25.29