
Reparatie mixer Grundfos MG 55-50-555, motor 6.9 kW/ 1500 rpm

I.D.: 64076764

Data publicarii	10.12.21	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 6.253,00 RON - 6.253,00 RON

Descriere: Reparatia consta in: - demontare si constatare; - bobinare motor 6.9 kW; - inlocuire rulmenti motor, rulmenti reductor, simeringuri, etansari mecanice, corp etansare; - montaj; - probe.
