
REPARATIE PULSOXIMETRU MASIMO

I.D.: 35360299

Data publicarii	17.04.19	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ:	3.095,80 RON - 3.095,80 RON
-------------------	-----------------------------

Descriere: CONSTATARE DEFECT * Inlocuire modul electronic citire sensor O2 * Inlocuire system alimentare,verificare electrosecuritate * PRELUARE,DEPANARE,RETUR,PROBE FUNCTIONALE
Tine loc de comanda ferma
