
Executat si inlocuit serpentina boiler 5000 L apa calda

I.D.: 41762431

Data publicarii	22.01.19	Coduri CPV	50531100-7
-----------------	----------	------------	------------

Pretul estimativ: 8.850,00 RON - 8.850,00 RON

Descriere: Oprit alimentare cu agent termic a serpentinei Demontat capac frontal si scos serpentina Executat serpentina (Tv 2"=66m, curbe 2"=22buc, tv Dn89mm=4m, electrozi=12kg) Inlocuit serpentina boiler 5000L Inlocuit garnitura D750mm Montat capac frontal Eexecutat legaturi agent termic si pornit alimentarea serpentinei cu agent termic Executat probe de presiune si etanseitate
