

## Servicii de reparare si intretinere

I.D.: 79378810

---

Data publicarii	02.03.23	Coduri CPV	50000000-5
-----------------	----------	------------	------------

---

Pretul estimativ: 1.089,92 RON - 1.089,92 RON

---

Descriere: SNUR DEMAROR (3.5 mm) - 2 M TAMBUR DEMAROR (135R, 333R) - 1 buc. FILTRU AER (333R) - 1 buc. ANSAMBLU CLICHET (122LD, 128C, 128R, 135R, 323C, 323R, 323RII, 325RX, 327PT5S) - 1 buc. GARNITURA Toba (135R, 333R) - 1 buc. AGATATOARE (535RX) - 1 buc. BUJIE Oregon CMR6H (T435, 545RX, 324RX, 550XP, 560XP, 562XP) - 2 buc. FILTRU AER (545RX, 545RXT) - 2 buc. TAMBUR DEMAROR (343R, 345Rx, 555Rxt, 555Fx) - 1 buc. FILTRU CARBURANT - 2 buc. AMBREIAJ (343R, 545RX, 545RXT) - 1 buc. CARCASA AMBREIAJ (343R, 345RX, 545RX, 545RXT) - 1 buc. ARC Ambreiaj (343R, 345RX, 555TXT, 555FX) - 3 buc. SITA CARBURATOR - 1 buc. MANOPERA Service - 5.7 ore

---