
REPARATII POMPE

I.D.: 43669864

Data publicarii	09.08.19	Coduri CPV	50511100-1
-----------------	----------	------------	------------

Pretul estimativ: 4.176,94 RON - 4.176,94 RON

Descriere: Reparatie pompa FLYGT 4,4 kW/3000rpm constand din: demontare pompa, extragere stator, rebobinare stator, prelucrare cota etansare, inlocuire kit etansare inferior si superior, montare, ermetizare, probe
