
REPARATIE LOGAN MCV - MAI 34322

I.D.: 42711311

Data publicarii	08.05.19	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 3.359,42 RON - 3.359,42 RON

Descriere: - schimbat chiulasa piese noua 2033.60 lei fara TVA - schimbat garnitura chiulasa 210.00 lei fara TVA - schimbat kit distributie, pompa apa, antigel - 899.15 lei fara TVA - schimbat ulei si filtru ulei - 216.67 lei fara TVA
