
Pachet reparatie masini de spalat pardoseli

I.D.: 34880120

Data publicarii	28.03.19	Coduri CPV	50111000-6
-----------------	----------	------------	------------

Pretul estimativ: 8.326,00 RON - 8.326,00 RON

Descriere: Reparatii masini de spalat pardoseli Karcher. Contine: - garnitura capac - 1 buc - garnitura motor - 1 buc - garnitura racleta - 1 buc - roti mari - 4 buc - roti mici - 4 buc - perie rosie - 2 buc - lamela antistropi - 1 buc - rola - 1 buc - rulment 6202 - 1 buc - suport - 1 buc - filtru apa - 2 buc - baterie 105Ah- 2 buc - duze - 5 buc - manopera - 8h
