
Servicii reparatie pompa apa conform deviz

I.D.: 52932316

Data publicarii	22.12.20	Coduri CPV	50110000-9
Pretul estimativ:	492,00 RON - 492,00 RON		
Descriere:	Extragere susuburi rupte din carcasa pompei ae apa Autobasculanta Volvo FM9-380 8x4 SB 06 ATU		
