
Reparatie Mercedes - CS-26-ACV

I.D.: 89886439

Data publicarii	22.11.23	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ:	25.638,65 RON - 25.638,65 RON
-------------------	-------------------------------

Descriere: Reparatie Mercedes - reparat cutie de viteze, inlocuit kit de ambreiaj complet (placa de presiune, disc de ambreiaj si rulment de presiune), inlocuit suruburi si piulite cardan.
