

---

## Reparatii ABS si bujie T5

I.D.: 41400274

---

Data publicarii	23.01.20	Coduri CPV	50112000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 1.185,71 RON - 1.185,71 RON

---

Descriere: Piесе/materiale Senzor ABS 1buc x 95,80 Rulment fata 1buc x 298,32 Sol curatat 2buc x 10,09 Bujie incandescenta OE 1buc x 109,24 Total piese/materiale 523,53 Manopera aferenta 662,18 TOTAL DEVIZ 1185,71 lei fara TVA

---