
Servicii de reparare uscator ind.IMESA

I.D.: 90817300

Data publicarii	13.12.23	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 970,00 RON - 970,00 RON

Descriere: Reparatie uscator de rufe industrial IMESA/ES10 ,inlocuit caseta cu rulment , reparat modul electronic la DGASPC SECTOR 1/ Centrul de zi "Iuliu"
