
Serviciul de reparatie motocultor BCS si servciul de reparatie motocoasa Stihl

I.D.: 52955680

Data publicarii	22.12.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 995,95 RON - 995,95 RON

Descriere: Serviciul de reparatie motocoasa FS 460 C si motocultor BCS 740 care consta in urmatoarele proceduri: - constatarea defectiunilor - identificarea pieselor defecte - inlocuirea pieselor defecte (ulei motor, ulei Bcs, filtru ulei transmisie, bujie, kit cutite freza, ulei 80w90, autocut 46-2, bujie, arc, rola demaror, sfoara demaror, clichet) - testare/predare
