

Verificare stingatoare

I.D.: 71949639

Data publicarii	03.08.22	Coduri CPV	50413200-5
-----------------	----------	------------	------------

Pretul estimativ:	1.930,00 RON - 1.930,00 RON
-------------------	-----------------------------

Descriere: Service hidrant interior: 13 buc x 55 lei Proba de presiune furtune: 13 buc x 55 lei Reparat robinet hidrant: 2 buc x 250 lei mai putin
