

---

## **Reparatie Dacia Duster CS07KSE- Inlocuire tubulatura senzor presiune**

I.D.: 60330136

---

Data publicarii	24.08.21	Coduri CPV	50112000-3
-----------------	----------	------------	------------

---

Pretul estimativ:	1.386,25 RON - 1.386,25 RON
-------------------	-----------------------------

---

Descriere:	Reparatie autoturism DACIA DUSTER nr. inmatriculare CS07KSE din parcul auto al OCPI Caras-Severin conform deviz nr. 157112
------------	--

---