
Reparatie sistem fierbator cazan abur ACD 0,5-6

I.D.: 49080768

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 21.08.20 | Coduri CPV | 50720000-8 |
|-----------------|----------|------------|------------|

Pretul estimativ: 7.860,00 RON - 7.860,00 RON

Descriere: Reparatie sistem fierbator la cazan de abur ACD 0,5-6, constand in inlocuirea unei tevi de fum, conform proiect de reparatie avizat RADTP.
