
Piese schimb pompa BELIN

I.D.: 102448169

Data publicarii	05.09.24	Coduri CPV	34324000-4 42124000-4
-----------------	----------	------------	-----------------------

Pretul estimativ:	37.464,92 RON - 37.464,92 RON
-------------------	-------------------------------

Descriere: Rotor tip "R" Pompa Bellin tip LG 1200M/PR = 2 buc, cod 34031203R, la Pret Unitar = 672 euro + TVA; Stator Pompa Bellin tip LG 1200M/PR = 2 buc, cod 710P1203, la Pret Unitar = 501 euro + TVA; Rotor Pompa Bellin tip LG 600C2/PRT = 2 buc, cod 34030607R, la Pret Unitar = 411 euro + TVA; Stator Pompa Bellin tip LG 600C2/PRT = 2 buc cod 710P0607/T, la Pret Unitar = 586 euro + TVA; Planetare /Cod 240301P0889/ arbore de transmitere a vitezei constante /in NBR-AC95/1MOD.N/L600C2/M/M2-N/L800M/L-N/E/L10001200M IN ACCIAIO C 40 COD 241 P-M080-S02 = 4 buc , la Pret Unitar = 792 euro + TVA;
