

---

## Reparatie Karcher HDS 558 Eco

I.D.: 54906434

---

Data publicarii	09.03.21	Coduri CPV	98390000-3 50111000-6
-----------------	----------	------------	-----------------------

---

Pretul estimativ: 2.475,00 RON - 2.475,00 RON

---

Descriere: Conditii neacceptate la termen: Reparatie curatitor cu presiune Karcher HDS 558 Eco conform deviz nr 6225 / 10.03.2020 - buton de pornire - 1 buc - furtun de presiune 20m - 1 buc - ulei motor 15W40 1L - 1 buc - roata ventilator - 1 buc - pana roata ventilator - 1 buc - rulment - 1 buc - set pompa - 1 buc - piston bypass - 1 buc - garnituri - 2 buc - garnituri - 2 buc - rulment - 1 buc - manopera 6h

---