

---

## Reparatii auto BH 15 SCB, VW Crafter

I.D.: 42356421

---

Data publicarii	29.03.19	Coduri CPV	50112100-4
-----------------	----------	------------	------------

---

Pretul estimativ: 5.150,50 RON - 5.150,50 RON

---

Descriere: Manopere: Constatare+Diagnosticare VW Crafter, Demontat-Montat filtru de particule, Reparare conducta senzor de presiune. Materiale: Filtru de particule

---