
Reparatie freza zapada FB5556A

I.D.: 50923198

Data publicarii	22.10.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 280,10 RON - 280,10 RON

Descriere: Reparatie freza zapada Proenerg FB5556A 10W4000000-ULEI MOTOR 4 TIMPI 10W40 LC171750002-ANS. REGULATOR TURATIE UP16810000204-CARBURATOR GG2900 UP16820004301-ARC REVENIRE ACCELERATIE UP16820004201-ARC REGULATOR TURATIE UP16820400000-SET SEGMENTI UP17020000900-GARNITURA BLOC MOTOR UP16820001800-GARNITURA CHIULASA MAN_SERV-Manopera reparatie in service TX_MD_UL-Taxa mediu ulei
