
SGA AR - Reparatie Motocoasa Stihl FS 90 deviz 3682 si Reparatie Motocoasa Stihl FS 310 deviz 3683

I.D.: 51734977

Data publicarii	16.11.20	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.070,59 RON - 1.070,59 RON

Descriere: Deviz de reparatie 3682 Capa Filtru aer FS 131, 235 Autocut 25-2 Stihl pentru motocoase Manopera (inclusiv reglat supape, curatat carburator) DEVIZ DE REPARATIE 3683 Roata pt cama FS 311 Semering DIN3760-AS12x22x7 Carburator FS 310 Filtru aer FS 131, 235 Pinion Sorb MS 170, 180 Aerisitor rezervor FS 56, 70, 131 conector 4180350140 Manopera
