

---

## **Kit de reparatie pentru mixer ABS RW 4032 A 40/8 EC**

I.D.: 52800010

---

Data publicarii	18.12.20	Coduri CPV	42124290-3
-----------------	----------	------------	------------

---

Pretul estimativ: 4.090,80 RON - 4.090,80 RON

---

Descriere: Kit de reparatie -mixer ABS RW 4032 A 40/8 EC cu seria 36663/MFY 2007- care include : rulmentii, O-ring-urile/garniturile si etansarile mecanice

---