
REPARATIE AUTO VW GOLF

I.D.: 84682448

Data
publicarii 13.07.23

Coduri CPV 50112200-5

Pretul
estimativ: 5.024,37 RON - 5.024,37 RON

Descriere: INLOCUIT CAPAC CULBUTORI CU FILTRU EPURATOR, GARNITURA CHIULASA, SIMERING AX CAME, PINION AX CAME, SUPAPE EVACUARE(8BUCATI) SIMERINGURI SUPAPE, GARNITURA GALESIE EVACUARE SI ADMISIE, ORINGURIINJECTOARE, GARNITURA POMPA VACCUM , RADIATOR INTERCOOLER+ VERIFICAT SI RECTIFICAT CHIULASA VW GOLF 5 DUPA 2008
