
Piese de schimb pentru mini-incarcatorul Locust L1203

I.D.: 96204318

Data publicarii	18.04.24	Coduri CPV	34300000-0 42950000-0
-----------------	----------	------------	-----------------------

Pretul estimativ: 3.002,36 RON - 3.002,36 RON

Descriere: Piese de schimb pentru reparatia utilajului multifunctional Locust L1203: -galerie evacuare - 1 buc; -piulita galerie evacuare -2 buc; -garnitura galerie evacuare -1 buc; -prezon galerie evacuare 60x8 mm -2 buc; -surub galerie evacuare 00222019 - 6 buc; -garnitura galerie evacuare 00226006 -2 buc; -prezon galerie evacuare 37x8 mm -4 buc; -garnitura chiulasa -1 buc; -cot cauciuc radiator -1 buc; -furtun radiator 00214010 -1 buc; -furtun radiator 08173015 -1 buc; -furtun radiator 00214035 -1 buc; -conducta radiator 00214037 -1 buc; -furtun radiator 00174083 - 1 buc; -furtun radiator 00214032 - 1 buc, Operatorul economic va asigura transportul gratuit al produselor la adresa indicata de autoritatea contractanta.
