
41X2234 maintenance fuser kit original Lexmark B2865 dw, MB2770 adhwe

I.D.: 86769103

| | | | |
|-----------------|----------|------------|-----------------------|
| Data publicarii | 06.09.23 | Coduri CPV | 30124200-6 30237000-9 |
|-----------------|----------|------------|-----------------------|

Pretul estimativ: 788,00 RON - 788,00 RON

Descriere: Kit de întreținere 225K 41X2234 ORIGINAL OEM 230V •41X1116—Fuser kit •41X1108—3 role de preluare •41X1119—3 separatoare de tăvi •41X1076—Rolă de transfer Lexmark B2865dw, MB2770adhwe / MS 725 dvn, 821 dn, 822 de, 823 dn, 823 n, 826 de / MX 721 ade, 721 adhe, 822 adxe, 826 ade / XM 7355, 7365, 7370
