
Servicii refacere sistem supraveghere sali de clasa - Hikvision 25camere

I.D.: 98321198

Data publicarii	03.06.24	Coduri CPV	50610000-4
-----------------	----------	------------	------------

Pretul estimativ: 30.000,00 RON - 30.000,00 RON

Descriere: Echipamente si materiale 1 Cablu Ftp cat 5e ml 900 2 Camera Hikvision dome 4k buc 10 3 Camera supraveghere Hikvisin dome cu sunet buc 20 4 Rack suspendat 4U buc 1 5 NVR Hikvisin 32 canale buc 1 6 HDD 6TB WD Surveillance buc 2 7 HDD 4TB WD Surveillance BUC 3 8 Switch 16 porturi Poe buc 4 9 Mufa RJ45 buc 50 Manopera 1 Montare doza buc 30 2 Montare camera buc 30 3 Sertizare mufa rj 45 buc 60 4 Configurare switch buc 4 5 Configurare camera buc 30 6 Configurare NVR buc 3
