

## **Materialele- Reparatii pereti si acoperis cladire administrativa**

I.D.: 96524128

Data publicarii 25.04.24 Coduri CPV 44100000-1

Pretul estimativ: 20.900,85 RON - 20.900,85 RON

Descriere: Fereastră pvc 1360x1890 2bucx1092.44, fereastră pvc 1400x1920 2bucx1084.03, fereastră pvc 680x1450 1bucx319.33, fereastră pvc 180x160 1bucx504.20, fereastră pvc 2bucx1197.48, usi pvc cu sticla 850x2000 1bucx966.39, vopsea clorcauciuc gri 4l 1bucx226.89, lac Wenge 1kg 7bucx31.09, lac pe baza de apa 1l 7bucx36.13, vopsea lavabila 15l 1bucx92.44, vopsea lav.ext.15l 3bucx344.54, diluant special 1bucx25.21, diluant 1l 1bucx10.08, pensula 70 2bucx7.56, pensula 50 1bucx5.88, set trafalet 1set x 12.61, rezerva trafalet 2bucx5.04, var 5 saci x 21.01, capse X20 20mlx1.26, placa rigips 12.5mm 28bucx33.61, imbinari rigips 3bucx25.21, banda rigips 2 x21.01, amorsa decorativa 5l 1gal x 54.62, profil CD 48bax x 13.45, spuma fixare 5bucx25.21, plasa polistiren 150mp x 2.52, polistiren EPS 80 5cm 8bax x 54.62, polist.ext.5cm 5bax x 21.01, coltar cu plasa 50bucx 5.46, corp led 4 buc x 29.41, priza dubla 3bucx 14.29, fisa CP 1bucx 10.08, cablu subteran 3x2.5 14mlx8.40, intr.cap scara 1bucx12.61, mufa al.1/2 1bucx5.04, mufa cu 28 1bucx4.20, mufa cu 18 1bucx1.68, mufa cu 35 2bucx12.61, doze aparataj 8bucx1.26, doza rigips 1bucx2.52, sir cleme 3set x 8.40, comutator 1bucx 11.76, jgheab maro 50ml x23.11, cot imbinare 6bucx 29.41, scurgere jgheab 4bucx 79.83, racord jgheab 4bucx37.82, bride 300bucx0.84, colier 2bucx1.68, bobite 500 x 0.04, surub lemn 4x40 500bucx0.08, surub lemn 4.5x80 200bucx0.25, surub rig.3.5x25 1000bucx0.06, surub 6x20 30bucx0.25, diblu 12x130 10buc x 1.09, ade.polistiren 30saci x